



PHONE CONVERSATION RECORD

CONVERSATION WITH:

NAME: Annette Cusher

DATE: 10 May 2013

TIME: 11:00

COMPANY: Arkansas Department of  
Environmental Quality (ADEQ)

CALL ORIGINATED BY: Michelle Brown,  
Weston Solutions, Inc.

PHONE: 501-682-0841

SUBJECT: Hayes Creek drainage ditches  
Norphlet, Union County, AR

A handwritten signature in black ink, appearing to read "Michelle Brown". The signature is fluid and cursive, with the first name "Michelle" written in a larger, more prominent script than the last name "Brown".

---

The drainage ditches located southeast of the former Ponds 710-712 and east of the wetland have water present in them, even the extreme draught conditions observed during field activities conducted in August 2012. A call to Annette Cusher of ADEQ was made to verify historical conditions of these ditches and Hayes Creek. ADEQ (formerly known as the Arkansas Department of Pollution Control and Ecology) has been visiting the site for the last 30 years. During this time, the ditches and Hayes Creek have always contained water. Although not identified on topographic maps, based on field observations, these ditches are actually a loop off the main Hayes Creek waterway and are therefore a perennial water body.